WITHAM FRIARY VILLAGE HALL

Date: 17/07/2022

What are the hazards?	Who might be harmed and how?	What are we already doing?	Do we need to do anything else to control this risk?	Action by who?	Action by when?	Done
Slips and trips in car park	Volunteers and visitors may be injured if they slip or trip over objects or uneven surface in the car park.	Car park surface maintained to be as even as possible. Adequate lighting in car park Adequate street lighting between car park and hall	. Car park surface to be inspected regularly and repaired as necessary Car park lighting to be inspected regularly and maintained as appropriate Street lighting to be observed regularly and any faults reported to Highways	RF	Weekly	Ongoing
Slips and trips on highway between carpark and village hall driveway	Volunteers and visitors may slip on mud deposited on road by farm vehicles	This is outside the control of the village hall committee as it is on the public highway but hirers will be made aware of the possible hazard	Monitor as part of regular inspection. Note in conditions of hire	RF	As necessary	Ongoing
Vehicle movement around village hall	Pedestrians could suffer serious injury if struck by vehicles entering or leaving car park or moving in it	Car park is adequately lit and street lamp is situated at the entrance	Advise users of hall that if they envisage large numbers of vehicles, they may need to control car parking Consider whether it is appropriate to display 5mph speed limit signs.	Advice ref parking to be included in conditions of hire. JH	September	Ongoing
Slips and trips on path to village hall entrance and steps into village hall.	Volunteers and visitors may be injured if they slip or trip over objects or uneven surface leading into hall	Adequate street lighting at entrance to village hall driveway Movement activated exterior light adjacent to steps into village hall. Driveway has recently been resurfaced. Steps are damaged	Regular checks of exterior light to ensure it is working. Repair edges of exterior steps and highlight	RF ?	Ongoing ASAP	Ongoing

Slips and trips on	Volunteers and visitors may be injured if	General good housekeeping is carried out.	Users to be informed through hire	All	Ongoing	Ongoing
spillages, trailing cables	they slip or trip over objects or spillages	All areas well lit.	agreement to clear up spillages.			
etc. within the hall	in the hall	No trailing leads or cables. Use of "Gaffer	Equipment to clear up spillages			
		Tape" to secure cables if necessary.	(mop/bucket etc.) to be readily			
		work areas to be kept clear e.g., no boxes	available and users made aware.			
		left in walkways	Weekly inspection to be carried out			
			and reported back to committee			
			Walkways and fire exit areas to be cleared			
			and maintained clear.			
			Check that suitable mats are placed at			
			entrance to prevent ingress of rainwater.			
Work at height e.g.,	Anyone working at any height could suffer	Ladders are available "on loan" from several members	Clarify what access equipment is readily	Committee	Next meeting	On going
changing light bulb,	injuries possibly very serious should they fall	of the committee	available e.g., ladder, commercial step ladder			
cleaning windows,			etc. and what controls are necessary for its			
putting up decorations			safe use. Egg Two people at all times etc.			
etc.			Print copies of HSE guidance on safe use of			
			ladders and step ladders and display as			
			appropriate.			
			Put in place system for checking condition of			
			access equipment			
			Consider whether it is necessary and			
			practicable to purchase suitable access			
			equipment.			
Hazardous substances	Anyone using cleaning products may risk skin	It is the policy of the committee to use where possible"	Ensure hazard data sheets are available for		Next meeting	*
e.g., cleaning products.	problems /eye damage from direct contact with	environmentally friendly" cleaning products but even	chemicals as appropriate and simple	RF/Commitee		
	cleaning chemicals. Vapor can cause breathing	so some of these products can be hazardous to	appropriate risk assessments available			
	problems.	people. Ongoing discussions are taking place as to				
		the best and most cost-effective way to maintain the				
	At present the amount the hall is used does not	cleanliness of the hall.				
	warrant a regular paid cleaner therefore users					
	are asked to clean up after them					

Electricity	Users risk shocks or burns from faulty equipment or installation. Poorly maintained	Fixed installation correctly installed by a competent electrician.	Ensure as part of hire agreement that users are aware of position of fuse boxes and which	Committee/RF	ASAP
	installation/equipment constitutes a fire risk.	Fixed installation inspected at appropriate intervals.	circuits they control and of how to switch off in emergency.		
			Ensure that all portable equipment belonging to the hall is inspected / tested as appropriate		
			Consider purchase of PAT tester.		
Stored equipment	Users could be injured by collapsing stacks of chairs/tables etc.	Checked during weekly inspection.	Check during weekly inspection. Ensure that users are made aware of correct	RF	ASAP
			method of storing/stacking.in conditions of hire.	JH	
Manual handling	Users could suffer back/muscle strain etc. if they try to lift objects that are too heavy or awkward	Users set up hall for use without assistance from Committee	Users to be reminded of the risk and offered assistance with setting up if necessary.	JH	ASAP
Asbestos	Asbestos only poses a risk if fibers are released. Maintenance workers are most at risk	The committee has been given to understand that due to its age and the periods when refurbishment was carried out there is no asbestos present in the building	Verify that this is the case. If proof is not available it may be necessary to carry out a type 1 survey before future renovation.	GMG	ASAP
Fire	Anyone in the building could suffer burns or fatal injuries from flames and smoke	Fire risk assessment has been carried out however the document is not available at present.	If risk assessment cannot be found ensure that a fire risk assessment is carried out ASAP and that recommendations are carried out	GMG/RF	Next meeting
Legionella	Anyone within the building could be at risk from inhalation of legionella if it is present and is spread in the form of droplets or mist (e.g., in showers)	A legionella risk assessment is in the process of being carried out.	Ensure that assessment is completed and that any appropriate action is taken	RF	Next meeting
Lone working	Users of the hall and volunteers could suffer accident whilst working alone in the building	Users and volunteers given advice.	Ensure that advice on lone working is given in terms of use	JH	Next meeting

Signed

.....